



VERTICAL SECTION OF
DOUBLE HUNG WINDOW
CHECK RAIL

Alternate Sill Detail